REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 7/12/2017 Time: 11:10 AM

Name of School Corporation: CARROLL CONS. SCHOOL CORP. Corp ID: 80750

Address of School Corporation: 2 S 3rd St.

City: Flora Zip: 46929 County Number: 8
VIN: 4DRBUAAP7CB590782 License Number: 3628 Bus Number: 17
Make of Body: IC Corporation Year: 2012 Make of Chassis: IC Corporation Year: 2012

Bus Type: C Mileage: 96722

Inspection Status: R Inspected By: Nate King PE: 7421

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

29-1-2 Floor covering is missing, cut, loose, buckled, bulging, or not secure

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.