

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 7/12/2017	Time: 11:25 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP.	Corp ID: 80750	
Address of School Corporation: 2 S 3rd St.		
City: Flora	Zip: 46929	County Number: 8
VIN: 4DRBUAAP87B397367	License Number: 30350	Bus Number: 9
Make of Body: IC Corporation	Year: 2007	Make of Chassis: IC Corporation
Year: 2007		
Bus Type: C	Mileage: 86030	
Inspection Status: R	Inspected By: Nate King	PE: 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.