## REPORT OF SCHOOL BUS INSPECTION

Type of 11:34 Time: Annual Date: 7/12/2017 Inspection: AM Corp ID: 80750

Name of School Corporation: CARROLL CONS. SCHOOL CORP.

**Address of School Corporation:** 2 S 3rd St.

County City: Flora Zip: 46929 8 Number:

License VIN: 1BAKECPH4AE271303 72274 **Bus Number:** Number:

Make of Blue Bird Blue Bird Year: 2010 Make of Body: Year: 2010 Corporation Chassis: Corporation

**Bus Type:** С Mileage: 75358

Inspection Inspected R PE: 7421 Nate King

Status: By:

## **Violations - Rejected**

## **Inspection Code Description**

46-1-5 Upholstery or padding is ripped, torn, or improperly repaired

Required back-up lights do not function. 2-1-1

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.