

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/12/2017	Time:	11:44 AM		
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.			Corp ID:	80750		
Address of School Corporation:	2 S 3rd St.						
City:	Flora	Zip:	46929	County Number:	8		
VIN:	4DRBUAAP56B231032		License Number:	21038	Bus Number:	15	
Make of Body:	IC Corporation	Year:	2006	Make of Chassis:	IC Corporation	Year:	2006
Bus Type:	C			Mileage:	107512		
Inspection Status:	O	Inspected By:	Nate King	PE:	7421		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
16-1-1	There are any leaks from the differential, pinion seal, or either rear wheel seal
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (½) inch in diameter.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.