

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/12/2017	Time:	11:51 AM		
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.			Corp ID:	80750		
Address of School Corporation:	2 S 3rd St.						
City:	Flora	Zip:	46929	County Number:	8		
VIN:	4DRBUAAPXBB334280	License Number:	75018	Bus Number:	24		
Make of Body:	IC Corporation	Year:	2011	Make of Chassis:	IC Corporation	Year:	2011
Bus Type:	C	Mileage:	76916	PE:	7421		
Inspection Status:	R	Inspected By:	Nate King				

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
59-1-4	LED type lights have 25% to 49% pixels inoperable in any one light. (NOTE: one letter in the word "STOP" equals one light)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.