## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	7/12/2017	Time:	12:12 PM
Name of School Co	orporation:	CARROLL CONS. SO	CHOOL CORP.		Corp ID:	80750
Address of School	Corporation:	2 S 3rd St.				
City:	Flora	Zip:	46929		<b>County Number:</b>	8
VIN:	4DRBUAAP16	B231030	License Number:	21037	Bus Number:	4
Make of Body:	IC Corporation	Year: 2006	Make of Chassis:	IC Corporation	Year:	2006
Bus Type:	С		Mileage:	73061		
Inspection Status:	R	Inspected By:	Nate King		PE:	7421

## **Violations - Rejected**

## Inspection CodeDescription46-1-5Upholstery or padding is ripped, torn, or improperly repaired

**Violations - Out of Service** 

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.