

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|--------------------------------|------------------------|--------------------|-------------------------|-----------|--------------|------|
| Type of Inspection: | Re-Inspection | Date: | 7/13/2017 | Time: | 7:48 AM | | |
| Name of School Corporation: | PRIMROSE SCHOOL OF NOBLESVILLE | Corp ID: | 290008 | | | | |
| Address of School Corporation: | 15707 North Point Blvd. | | | | | | |
| City: | Noblesville | Zip: | 46060 | County Number: | 29 | | |
| VIN: | 1GBHG31K091122207 | License Number: | B631E | Bus Number: | 3 | | |
| Make of Body: | Collins Bus Corporation | Year: | 2009 | Make of Chassis: | Chevrolet | Year: | 2009 |
| Bus Type: | | Mileage: | 48927 | | | | |
| Inspection Status: | A | Inspected By: | Jeff Kastenschmidt | PE: | 5805 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description