REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Re-InspectionDate:7/13/2017Time:9:40 AMName of School Corporation:ELWOOD COMMUNITY SCHOOL CORP.Corp ID:485280

Name of School Corporation: ELWOOD COMMUNITY SCHOOL CO
Address of School Corporation: 1306 N Anderson St

City:ElwoodZip:46036County Number:48VIN:4DRBUAFP97B415352License Number:10795Bus Number:26Make of Body:IC Corporation Year:2006

Bus Type: B Mileage: 59219

Inspection Status: A Inspected By: Jeremy Mason PE: 8139

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.