REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection		**Date:**	7/13/2017	**Time:**	9:40 AM
Name of School Corporation:	ELWOOD COMMUNITY SCHOOL CORP.				**Corp ID:**	485280
Address of School Corporation:	1306 N Anderson St					
City:	Elwood	**Zip:**	46036		**County Number:**	48
VIN:	4DRBUAFP97B415352		**License Number:**	10795	**Bus Number:**	26
Make of Body:	IC Corporation	**Year:** 2007	**Make of Chassis:**	IC Corporation	**Year:**	2006
Bus Type:	B		**Mileage:**	59219		
Inspection Status:	R	**Inspected By:**	Jeremy Mason		**PE:**	8139

Violations - Rejected

Inspection Code	Description
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.