

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 7/13/2017 **Time:** 10:06 AM
Name of School Corporation: ELWOOD COMMUNITY SCHOOL CORP. **Corp ID:** 485280
Address of School Corporation: 1306 N Anderson St
City: Elwood **Zip:** 46036 **County Number:** 48
VIN: 4DRBUAFP56B233341 **License Number:** 21084 **Bus Number:** 24
Make of Body: IC Corporation **Year:** 2006 **Make of Chassis:** IC Corporation **Year:** 2005
Bus Type: C **Mileage:** 66930
Inspection Status: O **Inspected By:** Jeremy Mason **PE:** 8139

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description
59-2-4 Stop arm does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.