

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	7/13/2017	<b>Time:</b>	11:21 AM
<b>Name of School Corporation:</b>	ELWOOD COMMUNITY SCHOOL CORP.	<b>Corp ID:</b>	485280		
<b>Address of School Corporation:</b>	1306 N Anderson St				
<b>City:</b>	Elwood	<b>Zip:</b>	46036	<b>County Number:</b>	48
<b>VIN:</b>	1GB6G2AG3A1147426	<b>License Number:</b>	83583	<b>Bus Number:</b>	A3
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2010	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>		<b>Mileage:</b>	50795		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Jeremy Mason	<b>PE:</b>	8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description