REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:** 7/13/2017	**Time:**	11:21 AM
Name of School Corporation:	ELWOOD COMMUNITY SCHOOL CORP.			**Corp ID:**	485280
Address of School Corporation:	1306 N Anderson St				
City:	Elwood	**Zip:**	46036	**County Number:**	48
VIN:	1GB6G2AG3A1147426		**License Number:** 83583	**Bus Number:**	A3
Make of Body:	Collins Bus Corporation	**Year:** 2010	**Make of Chassis:** Chevrolet	**Year:**	2010
Bus Type:			**Mileage:** 50795		
Inspection Status:	R	**Inspected By:**	Jeremy Mason	**PE:**	8139

Violations - Rejected

Inspection Code	Description
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

Violations - Out of Service

Inspection Code	Description

Bus Type Description