

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual                                 **Date:** 7/13/2017     **Time:** 11:51 AM  
**Name of School Corporation:** ELWOOD COMMUNITY SCHOOL CORP.             **Corp ID:** 485280  
**Address of School Corporation:** 1306 N Anderson St  
**City:** Elwood             **Zip:** 46036                                 **County Number:** 48  
**VIN:** 1GDHG31F3X1065346             **License Number:** 25960             **Bus Number:** A1  
**Make of Body:** Corbeil     **Year:** 1999             **Make of Chassis:** GMC             **Year:** 1999  
**Bus Type:**   **Mileage:** 53666  
**Inspection Status:** A                         **Inspected By:** Jeremy Mason             **PE:** 8139

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

Bus Type Description