

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 7/18/2017	Time: 9:39 AM
Name of School Corporation: NORTHEAST SCHOOL CORPORATION	Corp ID: 777645	
Address of School Corporation: PO Box 493		
City: Hymera	Zip: 47855	County Number: 77
VIN: 4DRBWAAR38A503274	License Number: 11227	Bus Number: 3
Make of Body: IC Corporation	Year: 2008	Make of Chassis: IC Corporation
Year: 2008	Mileage: 106015	PE: 7583
Bus Type: D		
Inspection Status: R	Inspected By: Tyler VanNess	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.