

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	8/1/2017	<b>Time:</b>	9:49 AM		
<b>Name of School Corporation:</b>	HUMAN SERVICES INC. HEAD START			<b>Corp ID:</b>	03003Z		
<b>Address of School Corporation:</b>	PO Box 119						
<b>City:</b>	Clifford	<b>Zip:</b>	47203	<b>County Number:</b>	3		
<b>VIN:</b>	1GB3G3BG3D1149429	<b>License Number:</b>	D463337	<b>Bus Number:</b>	1012		
<b>Make of Body:</b>	Chevrolet	<b>Year:</b>	2013	<b>Make of Chassis:</b>	Blue Bird Corporation	<b>Year:</b>	2013
<b>Bus Type:</b>	C	<b>Mileage:</b>	37921				
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Travis Coryea	<b>PE:</b>	5892		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.