REPORT OF SCHOOL BUS INSPECTION

Type of Time: Re-Inspection Date: 8/1/2017 9:49 AM Inspection:

Name of School HUMAN SERVICES INC. HEAD START 03003Z

Corp ID: Corporation:

Address of School Corporation: PO Box 119

County City: Clifford Zip: 47203 3 Number:

License VIN: D463337 **Bus Number:** 1GB3G3BG3D1149429 1012 Number:

Make of Blue Bird 2013 Make of Body: Chevrolet Year: 2013 Year: Chassis: Corporation

Bus Type: С Mileage: 37921

Inspected PE: **Inspection Status:** R Travis Coryea 5892 By:

Violations - Rejected

Inspection Code Description

29-1-2 Floor covering is missing, cut, loose, buckled, bulging, or not secure

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.