REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	8/2/2017	**Time:**	9:17 AM
Name of School Corporation:	SOUTH BEND COMM. SCHOOL CORP.			**Corp ID:**	717205
Address of School Corporation:	3003 N Bendix Dr				
City:	South Bend	**Zip:**	46601	**County Number:**	71
VIN:	4DRBUAAN9AB232062	**License Number:**	72400	**Bus Number:**	235
Make of Body:	IC Corporation **Year:** 2009	**Make of Chassis:**	IC Corporation	**Year:**	2010
Bus Type:	C	**Mileage:**	99829		
Inspection Status:	O	**Inspected By:**	Travis Harrold	**PE:**	8022

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	Description
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.