## **REPORT OF SCHOOL BUS INSPECTION**

| Type of<br>Inspection:         | Semi-Annual                 |                              |                  | Date:               | 8/3/2017  | Time:             | 8:43<br>AM |
|--------------------------------|-----------------------------|------------------------------|------------------|---------------------|-----------|-------------------|------------|
| Name of School Corporation:    |                             | WEST WASHINGTON SCHOOL CORP. |                  |                     |           | Corp ID:          | 888220     |
| Address of School Corporation: |                             | 9699 W Mt Tabor Rd           |                  |                     |           |                   |            |
| City:                          | Campbellsburg               |                              | Zip:             | 47108               |           | County<br>Number: | 88         |
| VIN:                           | 1GBHG31U841153926           |                              |                  | License<br>Number:  | 66961     | Bus Number:       | 60         |
| Make of Body:                  | Thomas Built Buses,<br>Inc. | Year:                        | 2004             | Make of<br>Chassis: | Chevrolet | Year:             | 2004       |
| Bus Type:                      | В                           |                              |                  | Mileage:            | 108285    |                   |            |
| Inspection Status              | : A                         |                              | Inspected<br>By: | Troy Boyd           |           | PE:               | 5171       |

## **Violations - Rejected**

Inspection Code Description

**Violations - Out of Service** 

Inspection Code Description

## **Bus Type Description**

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.