

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/17/2017	Time:	3:11 PM		
Name of School Corporation:	GARY COMMUNITY SCHOOLS			Corp ID:	454690		
Address of School Corporation:	3840 Georgia St						
City:	Gary	Zip:	46409	County Number:	45		
VIN:	4DRAPSKK69A674036		License Number:	B977H	Bus Number:	2	
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	A2			Mileage:	116995		
Inspection Status:	O	Inspected By:	Tim Grayson	PE:	7558		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-1	Required back-up lights do not function.
34-1-1	Any headlight is inoperative
33-1-4	See Notes: Any defect inspector deems a violation not listed
25-1-1	Mirror or mirror backs that are loose or improperly mounted
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
36-1-3	See Notes: Any defect inspector deems a violation not listed
64-1-4	Any front turn signal does not function properly
64-1-2	A lens is cracked, missing or wrong color

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.