

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |                |                         |           |
|---------------------------------------|--------------------------------|------------------------|----------------|-------------------------|-----------|
| <b>Type of Inspection:</b>            | Annual                         | <b>Date:</b>           | 8/28/2017      | <b>Time:</b>            | 10:57 AM  |
| <b>Name of School Corporation:</b>    | PIKE COUNTY SCHOOL CORPORATION |                        |                | <b>Corp ID:</b>         | 636445    |
| <b>Address of School Corporation:</b> | 907 Walnut St                  |                        |                |                         |           |
| <b>City:</b>                          | Petersburg                     | <b>Zip:</b>            | 47567          | <b>County Number:</b>   | 63        |
| <b>VIN:</b>                           | 1GB3G2BG5E1201221              | <b>License Number:</b> | 32030          | <b>Bus Number:</b>      | 51        |
| <b>Make of Body:</b>                  | Starcraft                      | <b>Year:</b>           | 2014           | <b>Make of Chassis:</b> | Chevrolet |
| <b>Year:</b>                          | 2014                           |                        |                | <b>Year:</b>            | 2014      |
| <b>Bus Type:</b>                      | B                              | <b>Mileage:</b>        | 18230          | <b>PE:</b>              | 7809      |
| <b>Inspection Status:</b>             | A                              | <b>Inspected By:</b>   | Bradley Miller | <b>PE:</b>              | 7809      |

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**