

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	8/29/2017	<b>Time:</b>	10:58 AM
<b>Name of School Corporation:</b>	NETTLE CREEK SCHOOL CORP.	<b>Corp ID:</b>	898305		
<b>Address of School Corporation:</b>	795 Baker Rd				
<b>City:</b>	Hagerstown	<b>Zip:</b>	47346	<b>County Number:</b>	89
<b>VIN:</b>	1HVBRABP92A940304	<b>License Number:</b>	18525	<b>Bus Number:</b>	15
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2001	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>	2001		<b>Year:</b>	2001	
<b>Bus Type:</b>	C	<b>Mileage:</b>	149687		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Jeremy Mason	<b>PE:</b>	8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
35-1-1	A heater motor is not operating properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
32-2-1	There is fuel leaking from any point on in the fuel system

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**