

# REPORT OF SCHOOL BUS INSPECTION

|                                |                           |               |                 |                  |                       |       |      |
|--------------------------------|---------------------------|---------------|-----------------|------------------|-----------------------|-------|------|
| Type of Inspection:            | Re-Inspection             | Date:         | 8/29/2017       | Time:            | 12:18 PM              |       |      |
| Name of School Corporation:    | NETTLE CREEK SCHOOL CORP. |               |                 | Corp ID:         | 898305                |       |      |
| Address of School Corporation: | 795 Baker Rd              |               |                 |                  |                       |       |      |
| City:                          | Hagerstown                | Zip:          | 47346           | County Number:   | 89                    |       |      |
| VIN:                           | 1BAKGCKH77F237871         |               | License Number: | 4724             | Bus Number:           | 17    |      |
| Make of Body:                  | Blue Bird Corporation     | Year:         | 2005            | Make of Chassis: | Blue Bird Corporation | Year: | 2007 |
| Bus Type:                      | C                         |               |                 | Mileage:         | 129071                |       |      |
| Inspection Status:             | R                         | Inspected By: | Jeremy Mason    | PE:              | 8139                  |       |      |

## Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 23-1-2                 | Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted) |
| 35-1-1                 | A heater motor is not operating properly   |

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.