

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	9/6/2017	Time:	9:28 AM
Name of School Corporation:	NORTH LAWRENCE COMM. SCHOOLS			Corp ID:	475075
Address of School Corporation:	595 Stars Blvd				
City:	Bedford	Zip:	47421	County Number:	47
VIN:	4DRBRAAN74B962946	License Number:	19551	Bus Number:	A25
Make of Body:	IC Corporation	Year:	2003	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	105931	Year:	2004
Inspection Status:	R	Inspected By:	Travis Coryea	PE:	5892

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
62-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.