

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 9/7/2017 **Time:** 9:48 AM
Name of School Corporation: EAST GIBSON SCHOOL CORPORATION **Corp ID:** 262725
Address of School Corporation: 941 S Franklin St
City: Oakland City **Zip:** 47660 **County Number:** 26
VIN: 1GB6G3AG8A1165037 **License Number:** 2369 **Bus Number:** 22
Make of Body: Star Trans **Year:** 2010 **Make of Chassis:** Chevrolet **Year:** 2010
Bus Type: **Mileage:** 67704
Inspection Status: **Inspected By:** Bradley Miller **PE:** 7809

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

Violations - Out of Service

Inspection Code Description

Bus Type Description