## REPORT OF SCHOOL BUS INSPECTION

| Type of<br>Inspection:                                     | Post-Crash Inspect       | tion   |                  | Date:              | 9/8/2017                 | Time:             | 1:39<br>PM |
|--|--------------------------|--|------------------|--------------------|--------------------------|-------------------|------------|
| Name of School Corporation: Address of School Corporation: |                          | NORTH DAVIESS CO. COMM. SCHOOL<br>5494 E SR 58 |                  |                    | Corp ID:                 | 141375            |            |
| City:  | Elnora                   |  | Zip:             | 47529              |                          | County<br>Number: | 14         |
| VIN:   | 1GBL7T1C71J508           | 775  |                  | License<br>Number: | B121E                    | Bus Number:       | 10         |
| Make of Body:  | Blue Bird<br>Corporation | Year:  | 2001             | Make of Chassis:   | Blue Bird<br>Corporation | Year:             | 2002       |
| Bus Type:  | С                        |  |                  | Mileage:           | Unknown                  |                   |            |
| Inspection<br>Status:                                      | 0                        |  | Inspected<br>By: | Kelly Hammond      |                          | PE:               | 6682       |

## **Violations - Rejected**

| <u>Code</u> | <u>Description</u>  |
|-------------|---|
| 20-1-2      | Excessive effort is needed to open the emergency door   |
| 23-1-1      | Any part is missing, including originally equipped heat shields   |
| 24-1-2      | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |
| 62-1-2      | One (1) taillight or one (1) brake light does not function  |

## **Violations - Out of Service**

| <u>Inspection</u><br><u>Code</u> | <u>Description</u>  |
|----------------------------------|---|
| 23-2-1                           | Exhaust leak exceeding one (1) inch measurable in any direction or half ( $\frac{1}{2}$ ) inch in diameter. |

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.