

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	9/19/2017	Time:	11:40 AM
Name of School Corporation:	CLAY COMMUNITY SCHOOLS	Corp ID:	111125		
Address of School Corporation:	PO Box 169				
City:	Knightsville	Zip:	47857	County Number:	11
VIN:	1BAKJCPA9HF329045	License Number:	12551	Bus Number:	39
Make of Body:	Blue Bird Corporation	Year:	2016	Make of Chassis:	Blue Bird Corporation
Bus Type:	C	Mileage:	16103	Year:	2017
Inspection Status:	O	Inspected By:	Tyler VanNess	PE:	7583

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
23-1-9	Tailpipe has been reduced in a size (diameter) from the rear of the muffler
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.