

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	9/21/2017	<b>Time:</b>	9:14 AM
<b>Name of School Corporation:</b>	BETHESDA BAPTIST CHURCH & SCHOOL			<b>Corp ID:</b>	323318
<b>Address of School Corporation:</b>	7950 N CR 650 E				
<b>City:</b>	BROWNSBURG	<b>Zip:</b>	46112	<b>County Number:</b>	32
<b>VIN:</b>	1BAKCKKA96F234080	<b>License Number:</b>	B958L	<b>Bus Number:</b>	4
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2005	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	44044	<b>Year:</b>	2005
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Jeff Kastenschmidt	<b>PE:</b>	5805

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
55-2-4	Tie rod end movement is greater than 1/8 inch (rotational movement is acceptable)
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
50-2-1	There is no seat belt cutter in the vehicle

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**