

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection Date: 9/21/2017 Time: 9:16 AM
Name of School Corporation: BETHESDA BAPTIST CHURCH & SCHOOL Corp ID: 323318
Address of School Corporation: 7950 N CR 650 E
City: BROWNSBURG Zip: 46112 County Number: 32
VIN: 1GDL7T1E82J509458 License Number: B891A Bus Number: 1
Make of Body: GMC Year: 2002 Make of Chassis: GMC Year: 2002
Bus Type: C Mileage: 107326
Inspection Status: O Inspected By: Jeff Kastenschmidt PE: 5805

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
62-1-10	See Notes: Any defect inspector deems a violation not listed
26-1-4	Not securely mounted

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
57-2-1	Any part of the step-well or support structure is rusted through

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.