

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	9/26/2017	<b>Time:</b>	9:57 AM
<b>Name of School Corporation:</b>	M.S.D. WABASH COUNTY SCHOOLS	<b>Corp ID:</b>	858050		
<b>Address of School Corporation:</b>	204 N 300 W				
<b>City:</b>	Wabash	<b>Zip:</b>	46992	<b>County Number:</b>	85
<b>VIN:</b>	4DRBUC8P2JB243973	<b>License Number:</b>	17781	<b>Bus Number:</b>	13
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2017	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>		<b>Year:</b>		<b>Year:</b>	2018
<b>Bus Type:</b>	C	<b>Mileage:</b>	1766		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-2	A lens is cracked, missing or wrong color
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-1	The front bumper does not extend to the edge of the fenders
34-1-5	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
36-2-1	The latch mechanism is missing
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
25-2-2	Reflective glass is cracked, broken, or missing

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**