

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 9/26/2017 Time: 9:57 AM
Name of School Corporation: M.S.D. WABASH COUNTY SCHOOLS Corp ID: 858050
Address of School Corporation: 204 N 300 W
City: Wabash Zip: 46992 County Number: 85
VIN: 4DRBUC8P2JB243973 License Number: 17781 Bus Number: 13
Make of Body: IC Corporation Year: 2017 Make of Chassis: IC Corporation Year: 2018
Bus Type: C Mileage: 1766
Inspection Status: O Inspected By: Randy McPike PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-2	A lens is cracked, missing or wrong color
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-1	The front bumper does not extend to the edge of the fenders
34-1-5	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
36-2-1	The latch mechanism is missing
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
25-2-2	Reflective glass is cracked, broken, or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.