

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|------------------------------|------------------------|--------------|-------------------------|--------------|
| Type of Inspection: | Post-Crash Inspection | Date: | 10/2/2017 | Time: | 11:11 AM |
| Name of School Corporation: | MANCHESTER COMMUNITY SCHOOLS | Corp ID: | 858045 | | |
| Address of School Corporation: | PO Box 308 | | | | |
| City: | North Manchester | Zip: | 46962 | County Number: | 85 |
| VIN: | 4UZAAXCT57CX72417 | License Number: | 30252 | Bus Number: | 14 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2006 | Make of Chassis: | Freightliner |
| Bus Type: | C | Mileage: | 106785 | | |
| Inspection Status: | R | Inspected By: | Randy McPike | PE: | 7018 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 90-1-3 | The trash container is not secured to prevent movement and does not allow for easy removal and replacement |
| 35-1-1 | A heater motor is not operating properly |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.