REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection		**Date:** 10/2/2017	**Time:**	11:11 AM
Name of School Corporation:	MANCHESTER COMMUNITY SCHOOLS			**Corp ID:**	858045
Address of School Corporation:	PO Box 308				
City:	North Manchester	**Zip:**	46962	**County Number:**	85
VIN:	4UZAAXCT57CX72417		**License Number:** 30252	**Bus Number:**	14
Make of Body:	Thomas Built Buses, Inc.	**Year:** 2006	**Make of Chassis:** Freightliner	**Year:**	2006
Bus Type:	C		**Mileage:** 106785		
Inspection Status:	R	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
35-1-1	A heater motor is not operating properly

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.