

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 10/10/2017      **Time:** 2:54 PM  
**Name of School Corporation:** EAST GIBSON SCHOOL CORPORATION      **Corp ID:** 262725  
**Address of School Corporation:** 941 S Franklin St  
**City:** Oakland City      **Zip:** 47660      **County Number:** 26  
**VIN:** 1GB6G3AG8A1165037      **License Number:** 2369      **Bus Number:** 22  
**Make of Body:** Star Trans      **Year:** 2010      **Make of Chassis:** Chevrolet      **Year:** 2010  
**Bus Type:**      **Mileage:** 69746  
**Inspection Status:** A      **Inspected By:** Bradley Miller      **PE:** 7809

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

Bus Type Description