REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		**Date:**	10/16/2017	**Time:** 8:26 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL				**Corp ID:** 141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	**Zip:**	47529		**County Number:** 14
VIN:	4UZAAXBV62CJ97773		**License Number:**	D784792	**Bus Number:** 16
Make of Body:	Freightliner	**Year:** 2001	**Make of Chassis:**	Freightliner	**Year:** 2002
Bus Type:	C		**Mileage:**	158845	
Inspection Status:	O	**Inspected By:**	Kelly Hammond		**PE:** 6682

Violations - Rejected

Inspection Code	Description
37-1-1	The horn does not operate at all
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

Inspection Code	Description
7-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit
70-2-3	Any emergency window will not open

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.