

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	10/16/2017	Time:	9:30 AM		
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			Corp ID:	141375		
Address of School Corporation:	5494 E SR 58						
City:	Elnora	Zip:	47529	County Number:	14		
VIN:	1BAKFCKH25F229144	License Number:		B896D	Bus Number:	18	
Make of Body:	Blue Bird Corporation	Year:	2004	Make of Chassis:	Chevrolet	Year:	2005
Bus Type:	C	Mileage:	95919				
Inspection Status:	R	Inspected By:	Kelly Hammond		PE:	6682	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-1	Required back-up lights do not function.
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
8-1-3	ABS warning light is illuminated

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.