REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	10/16/2017	**Time:**	10:50 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			**Corp ID:**	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	**Zip:**	47529	**County Number:**	14
VIN:	1FDWE35P55HA51789	**License Number:**	69262	**Bus Number:**	ND5
Make of Body:	Mid Bus, Inc. **Year:** 2005	**Make of Chassis:**	Ford	**Year:**	2005
Bus Type:		**Mileage:**	71160		
Inspection Status:	O	**Inspected By:**	Kelly Hammond	**PE:**	6682

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description