

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/16/2017	Time:	4:55 PM
Name of School Corporation:	EASTERN GREENE SCHOOLS	Corp ID:	282940		
Address of School Corporation:	RR 4 Box 351				
City:	Bloomfield	Zip:	47424	County Number:	28
VIN:	1HVBBABP54H580883	License Number:	17843	Bus Number:	7
Make of Body:	Blue Bird Corporation	Year:	2003	Make of Chassis:	IC Corporation
Year:	2004	Mileage:	76460		
Bus Type:	C	Inspected By:	Mark Raper	PE:	6473
Inspection Status:	O				

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
49-1-4	Any reflector is missing, cracked, faded, or the wrong color.
25-1-1	Mirror or mirror backs that are loose or improperly mounted
58-1-1	Any stirrup step or handle is broken, loose or missing
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-1	Any stop arm light is inoperative
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district).
3-2-3	Battery compartment door will not open. Key must be available if battery door is locked
63-2-3	Any tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.