

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Spot Checks      **Date:** 10/18/2017      **Time:** 8:18 AM  
**Name of School Corporation:** HANOVER COMM. SCHOOL CORP.      **Corp ID:** 454580  
**Address of School Corporation:** 14525 Wicker  
**City:** Cedar Lake      **Zip:** 46303      **County Number:** 45  
**VIN:** 1GB3B2BG3C1195996      **License Number:** 014189      **Bus Number:** 43  
**Make of Body:** Star Trans      **Year:** 2012      **Make of Chassis:** Chevrolet      **Year:** 2012  
**Bus Type:**      **Mileage:** 29032  
**Inspection Status:** R      **Inspected By:** Nathan Sherer      **PE:** 7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
17-1-1	Any dome light is inoperative
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

### Violations - Out of Service

Inspection Code Description

Bus Type Description