

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Spot Checks **Date:** 10/18/2017 **Time:** 8:18 AM
Name of School Corporation: HANOVER COMM. SCHOOL CORP. **Corp ID:** 454580
Address of School Corporation: PO Box 645
City: Cedar Lake **Zip:** 46303 **County Number:** 45
VIN: 1GB3B2BG3C1195996 **License Number:** 014189 **Bus Number:** 43
Make of Body: Star Trans **Year:** 2012 **Make of Chassis:** Chevrolet **Year:** 2012
Bus Type: **Mileage:** 29032
Inspection Status: R **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
17-1-1	Any dome light is inoperative
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code Description

Bus Type Description