

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 10/18/2017      **Time:** 8:36 AM  
**Name of School Corporation:** HANOVER COMM. SCHOOL CORP.      **Corp ID:** 454580  
**Address of School Corporation:** PO Box 645  
**City:** Cedar Lake      **Zip:** 46303      **County Number:** 45  
**VIN:** 1GB3B2BG3C1195996      **License Number:** 014189      **Bus Number:** 43  
**Make of Body:** Star Trans      **Year:** 2012      **Make of Chassis:** Chevrolet      **Year:** 2012  
**Bus Type:**      **Mileage:** 29032  
**Inspection Status:** A      **Inspected By:** Nathan Sherer      **PE:** 7029

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

Bus Type Description