

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 10/25/2017 **Time:** 10:00 AM
Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL **Corp ID:** 141375
Address of School Corporation: 5494 E SR 58
City: Elnora **Zip:** 47529 **County Number:** 14
VIN: 1FDWE35P55HA51789 **License Number:** 69262 **Bus Number:** ND5
Make of Body: Mid Bus, Inc. **Year:** 2005 **Make of Chassis:** Ford **Year:** 2005
Bus Type: **Mileage:** 71160
Inspection Status: A **Inspected By:** Kelly Hammond **PE:** 6682

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description