REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection		**Date:** 10/25/2017	**Time:**	10:00 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			**Corp ID:**	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	**Zip:**	47529	**County Number:**	14
VIN:	1FDWE35P55HA51789		**License Number:** 69262	**Bus Number:**	ND5
Make of Body:	Mid Bus, Inc. **Year:** 2005		**Make of Chassis:** Ford	**Year:**	2005
Bus Type:			**Mileage:** 71160		
Inspection Status:	A	**Inspected By:**	Kelly Hammond	**PE:**	6682

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description

Bus Type Description