REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Name of School Corporation:		NORTH ADAMS CO	Date: MM. SCHOOLS	11/1/2017	Time: Corp ID:	8:59 AM 10025	
Address of School Corporation:							
City:		Zip:			County Number:	1	
VIN:	4DRBVAAR96	A219843	License Number:	1389	Bus Number:	3	
Make of Body:	IC Corporation	Year: 2005	Make of Chassis:	IC Corporation	Year:	2006	
Bus Type:	D		Mileage:	103461			
Inspection Status:	0	Inspected By:	: Jamie Hotchkiss		PE:	6458	

Violations - Rejected

Inspection <u>Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code	Description
59-2-1	Any stop arm light is inoperative

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.