REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	ı		Date:	11/8/2017	Time:	9:46 AM
Name of School Address of School	Corporation: ool Corporation:		EWA C	COMM. SCHOOL n A St	CORP	Corp ID:	272855
City:	Gas City	Zip:		46933		County Number:	27
VIN:	4UZABRDU2BCAU21	22		License Number:	11366	Bus Number:	5
Make of Body:	Thomas Built Buses, Inc.	Year: 2009		Make of Chassis:	Thomas Built Buses, Inc.	Year:	2011
Bus Type:	С			Mileage:	62296		
Inspection Status:	0	Inspe By:	ected	Randy McPike		PE:	7018

Violations - Rejected

Inspection Code	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
34-1-5	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	<u>Description</u>
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.