

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	11/14/2017	<b>Time:</b>	10:17 AM
<b>Name of School Corporation:</b>	ORLEANS COMMUNITIY SCHOOLS			<b>Corp ID:</b>	596145
<b>Address of School Corporation:</b>	173 W Marley St				
<b>City:</b>	Orleans	<b>Zip:</b>	47452	<b>County Number:</b>	59
<b>VIN:</b>	1FDWE35P96HA51103	<b>License Number:</b>	68141	<b>Bus Number:</b>	20
<b>Make of Body:</b>	Mid Bus, Inc.	<b>Year:</b>	2005	<b>Make of Chassis:</b>	Ford
<b>Bus Type:</b>		<b>Mileage:</b>	57908	<b>Year:</b>	2006
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Kelly Hammond	<b>PE:</b>	6682

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-3	The handle guard is missing or bent
2-1-1	Required back-up lights do not function.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description