REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	11/15/2017	**Time:**	8:32 AM
Name of School Corporation:	HONEY GROVE EDUCATIONAL DAYCARE			**Corp ID:**	41001Z
Address of School Corporation:	1709 S SR 135				
City:	Greenwood	**Zip:**	46143	**County Number:**	41
VIN:	1GBHG31RXX1146766	**License Number:**	B958AB	**Bus Number:**	2
Make of Body:	Chevrolet **Year:** 1999	**Make of Chassis:**	Chevrolet	**Year:**	1999
Bus Type:		**Mileage:**	124932		
Inspection Status:	O	**Inspected By:**	John Pang	**PE:**	6196

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description