

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Semi-Annual                      **Date:** 11/15/2017   **Time:** 8:32 AM  
**Name of School Corporation:** HONEY GROVE EDUCATIONAL DAYCARE   **Corp ID:** 41001Z  
**Address of School Corporation:** 1709 S SR 135  
**City:** Greenwood   **Zip:** 46143                      **County Number:** 41  
**VIN:** 1GBHG31RXX1146766   **License Number:** B958AB   **Bus Number:** 2  
**Make of Body:** Chevrolet   **Year:** 1999   **Make of Chassis:** Chevrolet   **Year:** 1999  
**Bus Type:**    **Mileage:** 124932  
**Inspection Status:** O                      **Inspected By:** John Pang                      **PE:** 6196

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

#### Bus Type Description