REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 11/15/2017 Time: 8:32 AM Name of School Corporation: HONEY GROVE EDUCATIONAL DAYCARE Corp ID: 41001Z

Address of School Corporation: 1709 S SR 135

City:GreenwoodZip:46143County Number:41VIN:1GBHG31RXX1146766License Number:Bus Number:2Make of Body:Chevrolet Year:1999Make of Chassis:Chevrolet Year:1999

Bus Type: Mileage: 124932

Inspection Status: O Inspected By: John Pang PE: 6196

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description