

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	12/8/2017	Time:	8:55 AM		
Name of School Corporation:	WARSAW COMMUNITY SCHOOLS			Corp ID:	434415		
Address of School Corporation:	1 Administrative Dr						
City:	Warsaw	Zip:	46580	County Number:	43		
VIN:	4UZABRDT1CCBA1195		License Number:	2529	Bus Number:	111	
Make of Body:	Thomas Built Buses, Inc.	Year:	2011	Make of Chassis:	Freightliner	Year:	2012
Bus Type:	C			Mileage:	77495		
Inspection Status:	O	Inspected By:	Travis Harrold	PE:	8022		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-1	Any lens is cracked, missing, faded or of the wrong color
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.