

# REPORT OF SCHOOL BUS INSPECTION

|                                |                                |                 |               |                  |                          |
|--------------------------------|--------------------------------|-----------------|---------------|------------------|--------------------------|
| Type of Inspection:            | Spot Checks                    | Date:           | 12/8/2017     | Time:            | 8:52 AM                  |
| Name of School Corporation:    | LAPORTE COMMUNITY SCHOOL CORP. |                 |               | Corp ID:         | 464945                   |
| Address of School Corporation: | 200 Stevens                    |                 |               |                  |                          |
| City:                          | La Porte                       | Zip:            | 46350         | County Number:   | 46                       |
| VIN:                           | 4UZABRDC38CZ10884              | License Number: | 31238         | Bus Number:      | 7                        |
| Make of Body:                  | Thomas Built Buses, Inc.       | Year:           | 2007          | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type:                      | C                              |                 |               | Mileage:         | 118893                   |
| Inspection Status:             | O                              | Inspected By:   | Nathan Sherer | PE:              | 7029                     |

## Violations - Rejected

## Inspection Code Description

## Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 7-2-1                  | There is no brake certification form the certification is expired or is not signed within the six-month requirement |

## Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.